

I Pioli di fissaggio a saldare e avvitare per cremagliera art. 47


UK Fixing staves for rack 47

D Befestigung zum schweissen oder schrauben fuer 47

F Fixation à souder ou à visser pour crémaillere 47

E Travesaño de fijación para cremallera 47 para soldar o atornillar

RUS Крепеж под сварку или винты



Art. 48

avvitare - to screw
 schrauben - à visser
 atornillar - atornillar
 завинчивать

Art. 49

saldare - to weld
 zum schweißen - à souder
 soldar - soldar
 под сварку

| Articolo - Article | | Descrizione Description | L | L1 | F |  | |
|-------------------------|-------------|----------------------------|----|----|----|---|---|
| Riferimento - Reference | | | mm | | | N° |  |
| 48 | IZ 00 48 A0 | Avvitare | 25 | 10 | M8 | 30 | 1,7 |
| 49 | IZ 00 49 S0 | Saldare | 25 | / | / | 30 | 1,7 |